LEGAL DESCRIPTION SURVEYOR'S REAL PROPERTY REPORT ALBERTA LANDLOT 1, BLOCK 65, PLAN 1095F SCALE = 1:20010A STREET MUNICIPAL ADDRESS ASPHALT EDGE 91°12'04" 702 10th STREET, CANMORE Fd.I. 15.23 Disturbed FENCE ' PREPARED FOR DES ALPS ENTERPRISE ______ **NOTES** 6.78 EDGE OF DRIVEWAY IS 0.13 INSIDE LOT1 1. The survey was completed on ______ June 16 _____, 2017. 2. A title search was performed on _____ June 20 ____, 2017. 3. Unless otherwise specified, distances are taken to exterior finish of walls and are in metres. 4. Lot area ___612___m2 **GARAGE** $m_2^2 = 31 \%$ (Dwelling) (0.40 Eaves) Footprint 188 m² 8 % (Garage) m² 0.3 % 50 Cantilever 2.0 6. Fences are within 0.2m of property line unless otherwise shown. 6.78 DRIVEWAY FDGE 1.79 i 7. Eave measurements are to fascia. 8. Deck and stair measurements are to extents of walking surface. LOT 1 9. Registered interests (excluding encumbrances): 4.05 W. EDGE OF WALL EAVE EXTENDS 0.08 IS 0.24 INSIDE INTO 6th AVENUE. Certification: I hereby certify that this report, which includes the attached plan and related survey, was prepared and performed RAMP EXTENDS 0.06 LANDING INTO 6th AVENUE. (Up 3.6) under my personal supervision and in accordance with the the Alberta Land Surveyors' Association's Manual of Standard 1.23-Practice and supplements thereto. Accordingly, within those (Ramp) standards and as of the date of this report, I am of the DECK EXTENDS 0.10 LOT 2 the plan illustrates the boundaries of the property, the improvements as defined in Part D. Section 8.5 of the 1.25 EAVE Alberta Land Surveyors' Association's Manual of Standard AVENUE Practice, and registered easements and rights-of-way affecting 1.29 (Deck) the extent of the title to the property; 0.15 WIDE RESTAURANT 2. the improvements intended to be on the property are entirely FENCE IS 0.34 INSIDE LOT 2 within the boundaries of the property, except eave, deck and wheelchair ramp extend into 6th Avenue as shown; 0.35_ CANTI. 3. no visible encroachments exist on the property from any EAVE IS 0.40 improvements situated on an adjoining property; INSIDE LOT 2 4. no visible encroachments exist on registered easements or rights-of-way affecting the extent of the property. onsultum Cacanatics Purpose: This report and related plan have been prepared for the benefit of the property owner, subsequent owners, and any of their agents for the purpose of Services latd. a real estate transaction. Copying is permitted only for the benefit of these parties. Where applicable, registered easements and utility rights—of—way affecting the extent of the property have been shown on the plan. Unless shown otherwise, property corner markers have not been placed during the survey for this report. The plan should not be used to establish boundaries because of the risk of 12.25 EAVE EXTENDS 0.04 INTO 6th AVENUE DWELLING DECK 19. (Up 0.5) misinterpretation or measurement error by the user. The information shown on this report reflects the status of this property as of DECK EXTENDS 0.09 STEPS INTO 6th AVENUE the date of survey only. Users are encouraged to have the Real Property Report updated for future requirements. Lot boundaries have been determined prior to the survey completion date NOTE: SEE BACK FOR BLOCK INFORMATION. shown above. Therefore the present condition of survey evidence might be significantly different than that shown. Dated this 27th day of W. FDGE OF WALL IS 0.07 INSIDE FÉNCE 15.24 STREET McElhanney 91°11'29" BACK OF WALK CHECKED BY: GD Consulting Geomatics Services Ltd. DRAWN BY: PM JUNE-20-2017 Garret Dillabough, Alberta Land Surveyor 203 - 502 BOW VALLEY TRAIL, CANMORE AB, T1W 1N9 This document is not valid unless it bears an original signature and a RET-WALL EXTENDS PH (403) 678-6363; FAX (855) 407-3895 (C) McElhanney Consulting Geomatics Services Ltd. 2017 10th STREET permit stamp in a different colour than this document. FILE: 17-125 PAGE 1 OF 2

